

Inspection Cycle for Brick Chimneys



Q. What is the Recommended Inspection Cycle for Brick Chimneys?

The International Committee on Industrial Chimneys (CICND) has not produced guidance for the inspection cycle for brick chimneys.

ATLAS suggests that clients maintain a regular inspection cycle to ensure the continued safety of their chimneys, and the cycle should be increased to take in to account a significant change to the use of the building, local adverse weather conditions or concerns about the state of repair of the building.

ATLAS would suggest that in line with CICND's guidance on the inspection and maintenance of other types of chimney, brick chimneys are inspected annually for the first two years after commissioning or after a significant change of operation. Thereafter, ATLAS would suggest a minimum 3-yearly inspection cycle and immediately following fire and explosion.

This guidance note should be used in conjunction with the [ATLAS Guidance Note: Inspection and Maintenance of Concrete Chimneys and Cooling Towers](#) and the [ATLAS Guidance Note: Inspection of Single Flue Steel Chimneys](#).

Please note that any advice is given in good faith with the aim of providing general guidance on best practice. ATLAS and the individuals and organisations responsible for the advice do not accept any liability arising in any way from relying on it. If you require advice on a specific issue, you should seek your own independent professional advice.

ATLAS

Registered address: 167-169, Great Portland Street, 5th Floor, London W1W 5PF

AIMS Administration Centre: 7 Newton Place, Glasgow, G3 7PR

T: 0330 999 0026 E: info@atlas.org.uk

Company No. 5026089 Registered in England

VAT Registration No: 245 6019 69